PORT of MOSTYN

Mostyn | Flintshire | CH8 9HE
T: (01745) 560335
E: harbourmaster@portofmostyn.com
www.portofmostyn.co.uk

29th October 2026

Hydrographic Surveys of Mostyn Harbour Area and Salisbury Channel

Please find enclosed the surveys of the Harbour area and Salisbury Channel. Surveys were completed on 27th and 28th of October 2026, respectively.

Salisbury Channel

The Salisbury Channel least depth is **drying at 2.6m above chart datum, on the Western side of channel between S1 & S3 buoys.**

The boundaries are currently set at 110m.

Note: The channel is continuing to deepen, however a meander is developing as per above, and we will continue to monitor and if necessary shift lateral marker buoys accordingly.

Harbour

The current highest restriction within the Harbour Dredge Area (now annotated on the survey chart of the Harbour) is currently **3.2m above chart datum**, Northwest of M12 buoy.

Note: Whilst the above restriction is owing to slow build up in the vicinity of M12 buoy, the realistic navigational restriction is 1.8m above chart datum.

Mostyn Channel

Mostyn Channel was not surveyed as Salisbury remains the designated as the recommended channel.

Capt. Danny-Lee Davies AFNI
Harbour Master/Pilot
Port of Mostyn